



Harris County Water Control & Improvement District No. 36

903 Hollywood St. ● Houston, TX 77015

Phone 713-453-5493 ● Fax 713-453-4552

www.harriscountywcid36.com

"A RECOGNIZED SUPERIOR WATER DISTRICT"

Build New Home or Renovate a Mobile Home

New service taps have a separate instruction sheet.

You must have two inspections:

1. You must notify the District when the pipes are in the ground and **BEFORE** you pour the cement for the slab for the foundation.
2. You must notify the District when the P-Traps and vents are installed and **BEFORE** you put the sheet rock up for the walls.

These are some things that the inspector will be looking for:

- No direct connection between the public drinking water supply and where a potential source of contamination exists. Potential sources of contamination are isolated from the public water system by an air gap or an appropriate back flow prevention assembly in accordance with state Commission regulations.
- No cross-connection between the public drinking water supply and a private water system exists. Where an actual air gap is not maintained between the public water supply and a private water supply, an approved reduced pressure-zone back flow prevention assembly is properly installed and a service agreement exists for annual inspection and testing by a certified back flow prevention device tester.
- No connection exists which would allow the return of water used for condensing, cooling or industrial processes back to the public water supply.
- No pipe or pipe fitting which contains more than 8.0% lead exists in private water distribution facilities installed on or after July 1, 1988.
- No solder or flux which contains more than 0.2% lead exists in private water distribution facilities installed on or after July 1, 1988.

Interior of home in regards to the sewer lines.

- All sewer lines must be water tight. To make sure that no sewer will leak out of them.
- All plumbing appliances must have P-Traps and that they are properly ventilated to the outside.
- All plumbing must be to the Uniform Plumbing Code Standards.